

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

1171
East
> 1
1.548 mi.
8172 ft.

PRIVATE DWELLING
140 DOVER ST
BROOKLYN, NY

NY Spills S112809204
N/A

Relative:
Higher

Actual:
3 ft.

SPILLS:

Name: PRIVATE DWELLING
Address: 140 DOVER ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1214435 / 2014-08-11
Facility ID: 1214435
Facility Type: ER
DER Facility ID: 432977
Site ID: 477676
DEC Region: 2
Spill Cause: Storm
Spill Class: C3
SWIS: 2401
Spill Date: 2013-01-09
Investigator: TJDEMEO
Referred To: Not reported
Reported to Dept: 2013-01-09
CID: Not reported
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2013-01-09
Spill Record Last Update: 2014-08-11
Spiller Name: CARMINE CASDIL
Spiller Company: STORM DAMAGE
Spiller Address: Not reported
Spiller Company: 999
Contact Name: VINNIE LOVARI
DEC Memo: "1/10/2103 - Sangesland spoke to Vinnie at Island Tank. House was impacted by Sandy (1 block south of Sheepshead Bay). House has been on gas for 8 years, owner assumed tank was in the front lawn. Vinnie found the tank was in the basement behind a wall. Vinnie opened the wall, pumped out the tank and is now started to dig out the oil contaminated soil under the floor. Vinnie says he will get end points and prepare a report in 1-2 weeks. 8/11/14 TJD File review - site inspection performed 11/17/13. Site was damaged by flooding from Superstorm Sandy - basement 275 AST (under stairs) was compromised during flooding spilling an unknown volume of #2FO into basment. Owner retained the Services of Island Tank to perform the necessary cleanup. Property owner reports difficulty in obtaining information from contractor and reconstruction has not been completed at property, although owner states contractor has been paid in full. DeMeo left several messages (not returned) for contractor requesting closure documentation. At time of inspection the basement wood floor had been replaced and the spill area was backfilled with sand. A 4 inch monitoring well was in place under stairs in the reported spill area - DeMeo attempted to sample well with a bailer, however, the well was found to be dry (not installed in accordance with good

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

engineering practices). No petroleum odors were present inside of structure at time of inspection. Owner has been attempting to get contractor to return to complete the work - but has been unsuccessful. DeMeo took photographs of all owner's paperwork from Island Tank. No closure documentation has been received from contractor. Based upon inspection findings and interview with affected property owner - no further action is required. Photo file has been uploaded to DECDOCS. Spill closed."
"TANK REMOVAL, PUMPED OUT."

Remarks:

All Materials:

Site ID: 477676
Operable Unit ID: 1227475
Operable Unit: 01
Material ID: 2224829
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported